

PHILIPPINE GUARANTEE CORPORATION JOB ORDER

	-			
Auto Shop/Supplier	VALLEY SOUTH MOTORWORKS	J.O. No. :_	21.05.0013	
Address	1984 Angel Linao St., Brgy. 743, Malate, Manila	Date :	05.17.2021 2021-021	
TIN	175-722-874	RMRSV No. :_		
Telephone / Fax No	8404-1631	Date :	04.27.	2021
	following job/repair in accordance with the following			/
Particulars	Description	Quantity	Unit Cost	Amount
	LABOR Defective underchasiss For kilometer check up, tune up and change oil Machine Job: Press in and Press out For camber and alignment Straighten and align muffler assembly. Including muffler pipe Total Labor PARTS/MATERIALS Suspension lower bushing big (2pcs) Suspension lower bushing small (2pcs) Shock mounting (2pcs) Ball joint lower (2pcs) Clamp bushing (2pcs) Shock absorber (2pcs) Shock absorber (2pcs) Bushing stab link (4pcs) Muffler bushing (2pcs) Spark plug (4pcs) Oil filter (1pc) Air filter (1pc) Engine oil (5L) Total Parts/Materials Total Labor/Parts 12% VAT			4,500.00 1,500.00 2,500.00 1,200.00 3,500.00 1,530.00 3,960.00 1,980.00 4,320.00 11,400.00 700.00 1,200.00 1,200.00 1,200.00 1,200.00 1,50
	mount in Words: Fifty One Thousand Nine Hundred Fourte		P	51,914.80
The state of the s	nber: Toyota RAV ZGF 968	Company of the second s	Vorking Days upon rec	0.00 6. 00 0.000 0.000 0.000
Equipment/property numb	Jei.	Payment Term: 30 wo	orking days from receip	t of billing
LIBIOUS AVAILADICAL	/1	/		1

FUNDS AVAILABLE:

MERCEDITA C. LAPADA

Vice President, Budget Management Department

ROSEMARIE N. R Authorized Official

Vice President, Facilities and General Services Department

CONFORME:

VALLEY SOUTH MOTORWORKS

Signature Over Printed Name of Auto Shop / Supplier / Date

JOB COMPLETION AND ACCEPTANCE

This is to certify that the job /repair as stated above has been satisfactorily completed and